# **Improving hazard awareness** -hazard recap

## **ENGINE** ROOM

### **Missing section** of handrail, chain left hanging

Ζ

The simple, careless act of leaving the chain unhooked is a fall hazard for anyone passing.

#### Load on the chain J block exceeds the safe working load

The overloading of the chain block may result in the catastrophic failure of the equipment and injury to the crew.

#### **Dust bin with** overflowing oily rags near a hot running engine

Oily rags are a well-known fire hazard whereby the substances on the rags can ignite due to an exothermic reaction from the nearby hot engine, causing a fire.

### **Double-bottom tank** sounding pipe nonreturn device blocked in open position

4

An engine room may be flooded in the event of a collision or grounding that breaches the double-bottom tank if a sounding pipe non-return valve is blocked in the open position.

### Fuel oil tank in background with

## broken sounding glass

The broken sounding glass would allow for the content of the fuel oil tank to be emptied if at the same time the selfclosing valve is blocked in open position.

#### **Steam leaking** in pipe joint

O

Leaking steam poses a risk of serious burns to crew members working in the engine room.

#### Fuse box open with exposed wires

The exposed wires present the risk of electrocution. Electrical switchboards should always be properly closed and insulation matting provided.




# Loose floor

The missing floor plating may result in a crew member falling into the bilge spaces below the plating, causing serious injury.

### **Engine room** lighting damaged

C

ability of the crew to work engine room, which is a light source.



Broken lighting reduces the effectively and safely in the compartment with no natural

#### **Engineer walking** around engine room listening to iPod

By listening to loud music in the engine room the crew member risks not being able to respond to a command, alarm or safety critical situation that may arise.