

## 5. Engine room

This photograph shows a group of live wiring located in the engine room of a ship recently surveyed. It is probable that there have been major wiring modifications carried out without Class approval.

(The member was asked to rectify the situation in compliance of Class within a specified time and a follow-up survey carried out as confirmation).

On closer inspection, it can be seen that:

- · there are junctions in the wires
- some of the wiring outer covering is damaged and bare wires are showing

It is obvious even to the untrained eye that this wiring is:

- not safe
- · a significant electrical and fire hazard
- · not in compliance with Class rules
- not in compliance with Flag State rules
- · not in compliance with the ISM Code



There is no reason why this situation should have been allowed to continue without being rectified by the company. It is clearly a fire and personnel hazard, obvious to anyone inspecting the engine room.

## **Surveyor's notes summary**

The adherence to basic safety management techniques such as safe tank entry are fundamental to helping personnel stay safe on board. The use of permits to work must be in all safety management systems. Good housekeeping, making sure the ship is clean, tidy, free of residue and water on decks, free of litter and rubbish enhance the safety on board. Maintaining your fire-fighting and life saving appliances is not only a statutory duty, it is common sense. You may need to use them.

## **Safety & Loss Prevention Team**

Director of Loss Prevention Chris Spencer +44 20 3320 8807

chris.spencer@ctcplc.com

Chief Surveyor **Eric Murdoch**+44 20 3320 8836

eric.murdoch@ctcplc.com

Senior Surveyor **Julian Hines** +44 20 3320 8812 julian.hines@ctcplc.com

Surveyor Mark Ford +44 20 3320 2316 mark.ford@ctcplc.com Safety & Loss Prevention Executive Colin Legget +44 20 3320 2311 colin.legget@ctcplc.com

Surveyor Yves Vandenborn +65 6506 2896 yves.vandenborn@ctcplc.com Administrator
Christine Mills
+44 20 3320 8868
christine.mills@ctcplc.com

## **The Standard Club**

Standard Safety is published by the managers' London agents: Charles Taylor & Co. Limited Standard House, 12/13 Essex Street, London, WC2R 3AA England

Telephone: +44 20 3320 8888 Emergency mobile: +44 7932 113573 E-mail: p&i.london@ctcplc.com Please send any comments to the editor – Chris.Spencer@ctcplc.com Telephone: +44 20 3320 8807

standard-club.com

The information and commentary herein are not intended to amount to legal or technical advice to any person in general or about a specific case. Every effort is made to make them accurate and up to date. However, no responsibility is assumed for their accuracy nor for the views or opinions expressed, nor for any consequence of or reliance on them. You are advised to seek specific legal or technical advice from your usual advisers about any specific matter.

